



ADMINISTRATIVE NOTICE OF ORDINANCE VIOLATION

In the City of Chicago Department of Administrative Hearings
City of Chicago, a Municipal Corporation, Petitioner, vs.

Respondent *if Chicago Business, use name on license* Last Name, First Name MI
Quality Restorations Inc.

Resp. Address No. Dir. Street Name ST Suffix Apt./Ste.
356 **Tioga Trail**

City State ZIP
Wood Dale IL **60191**
 Other:

Person Served *if other than the respondent* Last Name, First Name MI

Phone Acct. No. or DREV No. on business license

Identification DLN/ID DLN State D.O.B. (M/D/Y)
 DLN/ID IL / /
 Other: Other:

Height Weight Sex Race Eyes Hair Service Request Number
 /

Officer, Investigator, Inspector, and/or Complainant on oath states that the Respondent did then and there violate the following section(s) of the Municipal Code of Chicago:

E000030955	COUNT	NUISANCE IN CONNECTION WITH A BUSINESS 7-28-080	COUNT	OTHER: TITLE CHA. SEC.	RULE
		DUMPING ON REAL ESTATE WITHOUT A PERMIT 7-28-440	Offense (if other):		
	1	HANDLING OF MATERIAL SUSCEPTIBLE TO BECOMING WINDBORNE (a) 11-4-760			
		TREATMENT AND DISPOSAL OF SOLID OR LIQUID WASTE 11-4-1500	COUNT	OTHER: TITLE CHA. SEC.	RULE
		SANDBLASTING, GRINDING, CHEMICAL WASHING VIOLATION 11-4-2190	Offense (if other):		
		RECYCLING FACILITY PERMIT 11-4-2520			
	CONSTRUCTION SITE CLEANLINESS () 13-32-125(2)				

You Must Describe Actions for Each Count below:

15 Count 1, In That: **Respondent failed to take reasonable precautions to minimize windborne particulate matter.**

Count 2, In That:

Violation Location Nos. Dir. Street Name *in the City of Chicago, County of Cook* ST Suffix
111 **Echestnut** **ST**

Vio. Date: Mo/Day Year Time of Violation AM PM Notice Date: Mo/Day if different than Vio. Date Year of Notice
11/25/2019 **10:30** **20**

Complainant's Name *if not issuing officer, investigator, or inspector* Environment Version 05-13
Environment

Unit Star Badge Signature of issuing officer, investigator, or inspector
P&E **39X** **Jane Suter**

Administrative Hearing Appearance

IMPORTANT: You must appear for a mandatory hearing on:

Date: Mo/Day Year Time AM PM at: 400 W. Superior Room No.
02/13/2020 **1:00** **112**

FAILURE TO APPEAR may result in the imposition of a fine not to exceed the maximum penalties for each violation as specified in the Municipal Code of Chicago plus costs, restitution, and fees. Failure to comply with the administrative law judge's order may result in the issuance of additional sanctions.

I acknowledge receipt of this notice.
 Signature of Respondent or Person Served: **X** **E**

Comments
Served via U.S. Mail



JH

**CITY OF CHICAGO
DEPARTMENT OF PUBLIC HEALTH**

NARRATIVE EVALUATION


Address:	<u>111 E CHESTNUT ST, CHICAGO, IL 60611</u>	Date:	<u>11/26/2019</u>
Inspector:	<u>JOHN SINGLER / FRANCISCO Flores Silva</u>	Time:	<u>11:40 am to 12:40 pm</u>
Complaint Number:	<u>600759457</u>	Log #:	<u>10603232</u>

On November 26, 2019 Chicago Department of Public Health (CDPH) inspectors John Singler and Francisco Flores Silva (we) responded to a 311 sandblasting complaint located at 111 E Chestnut St. Upon arrival the inspectors took photographs of the building permits and air permit "Architectural Surface Cleaning Permit". The inspectors noted the contracting firm written on the air permit was Quality Restorations Inc. The reporting inspectors contacted and met with the complainant. The complainant then proceeded to inform us that the construction company was not sandblasting but rather was performing grinding activities. The complainant alleged that the contracting firm hired by the building's association performing the grinding activities were not utilizing dust minimization measures in the form of vacuum attachments or water and were therefore generating dust plumes. The complainant then showed the reporting inspectors photographic evidence of the alleged violations. After reviewing the photographs, the reporting inspectors concluded that the contracting firm (QUALITY RESTORATIONS INC.) did commit a violation. The complainant was asked if he/she would sign for the citation and testify as witness in case of a hearing. Mr. Brian Connolly (complainant) agreed and is credited for providing evidence that demonstrates the violation taking place. Mr. Connolly explained that the photographic evidence of the violation was taken on November 25, 2019 the date can be referenced on the "Photo Date" of the attached photographs. The responding inspectors then proceeded to speak to the property manager (Sudler Property Management). The inspectors informed the property manager that QUALITY RESTORATIONS INC (Quality). needed to implement dust minimization measures and that a citation was going to be issued to Quality. The inspectors also informed Quality via telephone about the citation that they are receiving and the need to implement dust minimization measures. Multiple addresses were listed and the reporting inspectors also asked Tom Steele (Quality Restorations Inc.) what address would be the best to send the citation to and he responded to send the citation to P.O. Box 792 Wood Dale IL, 60191. The citation is for Handling and Storage of Material Susceptible to Becoming Windborne 11-4-760(a). Citation number is E000030955 15. The hearing date is February 13, 2020.

I, JOHN SINGLER, an employee of the City of Chicago, Department of Public Health, declare that I have conducted an inspection of the above mentioned property on the date indicated. I further declare that the observations set forth on the report are true and accurate.

39

STAR #



SIGNATURE



Department of Public Health
Inspector Photo Log

Address: 111 E CHESTNUT ST
Inspector: JOHN SINGLER

Photo Date: 11/26/19 F.F
Service Request #: 600759457



COMMENTS: Photo E- 111 E. Chestnut St., Site Sketch

Address: 111 E CHESTNUT ST
Inspector: JOHN SINGLER

Photo Date: 11/25/19 F.F
Service Request #: 600759457



COMMENTS: Photo A- 111 E. Chestnut St., Photo of worker grinding on scaffold outside Mr. Conolly's apartment. Dust can be seen.



Department of Public Health
Inspector Photo Log

Address: 111 E CHESTNUT ST
Inspector: JOHN SINGLER

Photo Date: 11/25/19 F.F
Service Request #: 600759457



COMMENTS: Photo B- 111 E. Chestnut St., Photo*of worker grinding. Dust plume can be seen.

Address: 111 E CHESTNUT ST
Inspector: JOHN SINGLER

Photo Date: 11/25/19 F.F
Service Request #: 600759457




COMMENTS: Photo C- 111 E. Chestnut St., Photo of worker using a grinder. No water or vacuum can be seen.




Department of Public Health
Inspector Photo Log

Address: 111 E CHESTNUT ST
Inspector: JOHN SINGLER

Photo Date: 11/26/19 F.F.
Service Request #: 600759457



COMMENTS: Photo D- 111 E. Chestnut St., Photo of Architectural Surface Cleaning permit.



*** Not drawn to scale. Aerial imagery may not be representative of actual site conditions at the time of inspection.



SITE SKETCH
 CITY OF CHICAGO
 DEPARTMENT OF PUBLIC HEALTH
 PERMITTING AND INSPECTIONS

DATE:	11/26/2019
TIME:	11:40 A.M.- 12:40 P.M
SITE ADDRESS:	111 E. Chestnut St.
SITE CODE:	
INVESTIGATOR:	J.Singler/F. Flores Silva
COUNTY:	COOK COUNTY/CHICAGO